


Rec'd PCT/PTO 17 JUN 2005
 10/540083


Figure 1



BEST AVAILABLE COPY

Rec'd PCT/PTO 17 JUN 2005
10/540083

Figure 2



Rec'd PCT/PTO 17 JUN 2005
10/540082

Figure 3




Figure 4






Figure 5




wire guides not shown

Figure 6



wire guides not shown



Rec'd PCT/PTO 17 JUN 2005
10/540083



Rec'd PCT/PTO 17 JUN 2005
10/540083




Figure 9

Figure 10




Figure 11





Figure 12







Figure 13



Inventor: Carney et al.
Title: CONNECTOR MODULE
Docket: 587-500 PCT/US
Sheet 15 of 23
Express Mail # ED381139323 US




Figure 14B

Rec'd PCT/PTO 17 JUN 2005
10/540083




Figure 15

Rec'd PCT/PTO 17 JUN 2005

10/540083




Figure 16





Figure 17

10/540083






Figure 19




Figure 20A





Figure 20B

Figure 21



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.